



2024 GAS LIFT WORKSHOP

Erosion Testing of Gas Lift Check Valves for Unconventional Applications



Michael Romer and Adrian Lejeune – ExxonMobil Upstream Integrated Solutions

Tom “The Reaper” Murray – ExxonMobil Technology and Engineering

Justin Lapointe – ExxonMobil Upstream Oil & Gas

Michael Juenke and Rick Haydel – ELC Energy

Anthony Mason, Dylan Bucanek, and Rick Webb – Endurance Lift Solutions

Stephen Burrows and Matt Young – Flowco Production Solutions

Mike Leonard and Ben Jirasek – Mako Lift

Brian Sternaman, Dean Gordon, Mike Johnson, and Humberto Machado – Weatherford



ALRDC.COM



2024 GAS LIFT WORKSHOP

- Background
- API 19G2 Check Testing
- Test Plan
- Flow Loop
- Water Results
- Sand Results
- Summary / Next Steps

Outline

ALRDC.COM


Aug. 5, 1958

H. U. GARRETT ET AL
GAS LIFT MANDREL AND VALVE

2,845,940

Filed Feb. 18, 1953

2 Sheets-Sheet 1



Henry U. Garrett
Clifford M. Peters
INVENTORS

BY *Browning & Simms*

ATTORNEYS

Background

Conventional GLVs

- Over 1400 ExxonMobil Permian wells are on GL
- Majority of installations have conventional mandrels with 1" GLVs (thanks to 5.5" casing)
- A common cause of tubing-annulus communication is failed reverse-flow check valves
- Tubing pulls can be costly, especially if the production packer doesn't release
- So, just clean up the fluids, right?

Producing Method Well Count by BU



ALRDC.COM

Background

Fracturing

- Unconventional wells are hydraulically fractured with > 2500 lb proppant / lateral ft
- That's > 13 million lb / mile, enough to fill 2 US football fields 1ft high...most laterals are > 2 miles!
- Some sand will remain in the well and more will be produced—is removing it all a feasible goal?
- No matter how clean your unloading fluids are, 100-mesh sand can and will find the GLVs
- Annular- / tubular-flow GL swaps do not help
- So, the GLV checks must be able to resist solids



API SPEC 19G2 Check Testing

19G2 = Flow-Control Devices for Side-Pocket Mandrels

- API Specification for GLVs used in SPMs (1st ed., Jun 2010)
- SPMs initially developed when GL went offshore in the 1960s+
- Various Validation (V), Functional (F), and Quality (Q) grades
- Commonly specified for offshore GL (EM East Canada and Indonesia, recently)

Annex K.3 = Reverse-Flow Check Erosion Test

- Liquid tests for retrievable GLV checks (gas testing also required in Annex H)
- V2/V1 Test: 1 bbl/min for 400 bbl of **fresh water**
- Passing Criteria
 - “No pressure drop over a 1 min hold-period”
 - “~~No damage to the back-check valve~~, and the dart should move freely from open to closed position and from closed to open position without human intervention”

Flow-control Devices for Side-pocket
Mandrels

API SPECIFICATION 19G2
SECOND EDITION, SEPTEMBER 2020


API MONOGRAM PROGRAM EFFECTIVE DATE: MARCH 12, 2021





2024 GAS LIFT WORKSHOP

Water? How About
Some Sand for Fun...



- Goal is 1% (by weight) sand erosion testing at 1 bbl/min for 400 bbl
- Attempted 0.5 bbl/min for “easier” test, but found that sand dropped out of solution
- Minimum injection rate for suspension is 0.6 bbl/min
- 70/100 mesh sand replaced every few runs to ensure angularity



ALRDC.COM

Test Plan

1. Chattering

- Test with air at low dp to determine whether the check chatters
- Informational test – haven't noticed chatter, yet

2. Water "Erosion"

- 400 bbl water at 1 bbl/min
- Reverse-flow seal tests every 100 bbl, if it passes all 4, then

3. Sand Erosion, Low Rate

- 400 bbl water with 1% sand at 0.6 bbl/min
- Seal tests every 100 bbl, if it passes all 4, then

4. Sand Erosion, High Rate

- 400 bbl water with 1% sand at 1 bbl/min
- Seal tests every 100 bbl, if it passes all 4, then it's done!





2024 GAS LIFT WORKSHOP




EMTEC Friendswood Testing Facility

NASA
15 min.






2024 GAS LIFT WORKSHOP



Front

Flow Loop


GLV Test Skid



Back



Flow Test
Flow Into
Dart Tip



Seal Test
Outlet Flow

Inlet Flow

Flow Test
Outlet Flow



Seal Test
Flow Into
Spring



2024 GAS LIFT WORKSHOP

Model B.A

Water “Erosion” Results

What “good” looks like...



PT2 and PT3 do not equalize during the seal test

ALRDC.COM



2024 GAS LIFT WORKSHOP


Other failure had a “unique” sealing design, improvements identified

Water “Erosion” Results

Model C.A



Make	Model	Size	Change	Assembly	Rnd	Date	Water
A	A.0	1	-	Single	1	Jul-23	Yes
	A.1	1	Coating	Single		Jul-23	Yes
	A.2	1	Coating	Single		Jul-23	Yes
	A.0	1	-	Dual		Jul-23	-
	A.1	1	Coating	Dual		Jul-23	-
	A.2	1	Coating	Dual		Jul-23	-
B	A	1	-	Single	1	Mar-23	Yes
	B	1	Materials	Single	2	Aug-23	Yes
	C	1	Geometry	Single	3	Feb-24	Yes
	D	1	Geometry	Single		Feb-24	Yes
C	A	1	-	Single	1	Mar-23	No
	B	1	Pressure	Single		Mar-23	Yes
	C	1	Geometry	Single		Mar-23	Yes
D	A.0	1	-	Single	1	Nov-23	Yes
	A.1	1	Coating	Single		Nov-23	Yes
	A.0	1.5	-	Single		Nov-23	Yes
E	A	1	-	Single	1	Feb-23	Yes
	B	1	Geometry	Single	2	Jul-23	Yes
	B	1.5	Geometry	Single		Aug-23	Yes



5K(psi) check dart jammed in the body and had to be punched out, some had missing/broken springs. All others tested were 10K

ALRDC.COM




2024 GAS LIFT WORKSHOP

Model E.A

Sand Erosion Results

What wear looks like (1 bpm)...



PT2 = PT3 = No Seal


ALRDC.COM



2024 GAS LIFT WORKSHOP

Model B.A

Sand Erosion Results



ALRDC.COM

Sand Erosion Results – Not Passing

Make	Model	Size	Change	Assembly	Rnd	Date	Water	Pass?	
								Sand 0.6	Sand 1.0
A	A.0	1.0	-	Single	1	Jul-23	Yes	No	-
	A.1	1.0	Coating	Single		Jul-23	Yes	No	-
	A.2	1.0	Coating	Single		Jul-23	Yes	No	-
	A.0	1.0	-	Dual		Jul-23	-	No	-
	A.1	1.0	Coating	Dual		Jul-23	-	No	-
	A.2	1.0	Coating	Dual		Jul-23	-	No	-
B	A	1.0	-	Single	1	Mar-23	Yes	No	-
	B	1.0	Materials	Single	2	Aug-23	Yes	No	-
	C	1.0	Geometry	Single	3	Feb-24	Yes	No	-
	D	1.0	Geometry	Single		Feb-24	Yes	Yes	No
	E	1.0	Geometry	Single		Feb-24	No	-	-
C	A	1.0	-	Single	1	Mar-23	No	-	-
	B	1.0	Pressure	Single		Mar-23	Yes	No	-
	C	1.0	Geometry	Single		Mar-23	Yes	No	-
D	A.0	1.0	-	Single	1	Nov-23	Yes	No	-
	A.1	1.0	Coating	Single		Nov-23	Yes	No	-
	A.0	1.5	-	Single		Nov-23	Yes	Yes	-
E	A	1.0	-	Single	1	Feb-23	Yes	No	-
	B	1.0	Geometry	Single	2	Jul-23	Yes	No	-
	B	1.5	Geometry	Single		Aug-23	Yes	Yes	Yes

General

- No seal after flushing = failure
- Sealing after punching free still = failure
- Failure modes mimicked those seen in equipment pulled from the field
- Dual checks did not solve the problem

Failure Modes

- Eroded/cut sealing faces
- Broken/missing springs
- Solids sticking (holding open)
- Bored/fluted flow paths
- Cascading debris




2024 GAS LIFT WORKSHOP

Sand Erosion Results

Note check housing “fluting” in line with the flow ports; results shown at 0.6 bpm unless specified otherwise

Check Valve Assembly



Valve Housing



Dart & Washer Assembly





2024 GAS LIFT WORKSHOP

Sand Erosion Results

Note dart erosion, polishing/wear and “unsticking” punch

Valve Seal Housing Assembly



Valve Body without Seal after 200BBL Erosion Test



Bottom Housing Assembly



Valve Housing Eroded



Polished Opening Eroded ~0.156"



Inlet Top Housing



Polished Opening Eroded ~0.156"



Dart & Seal Assembly



Seal Pad Eroded Pattern at Dart Tip



Dart & Seal Assembly



Dart Erosion Post 200BBL

Dart After & Before 200BBL Erosion Test

Punch Set Used to Free the Dart then Flush Assembly Before Seal Integrity Test





2024 GAS LIFT WORKSHOP

Sand Erosion Results



Broken / missing springs
in after/before photos

ALRDC.COM



2024 GAS LIFT WORKSHOP

Sand Erosion Results

Dart & Washer Assembly

Check Valve Assembly

Dart Tip Erosion


Valve Housing



Seal Pad and Washer Worn After 400 BBL



Check Valve Assembly After 400 BBL



Valve Top Housing Polished



After & Before 400 BBL




Seal Pad

Note seal face changing from a sphere to a cone

After 400 BBL 1% Sand Erosion

Sand Erosion Results – Dual Checks

If one is good, then two are better, right?





2024 GAS LIFT WORKSHOP



Sand Erosion Results – Dual Checks

- Higher injection pressure at same rate appears to have destroyed check springs more quickly
- Dual checks failed seal testing 200 bbl **earlier** (sticking) than a single check
- Broken upper spring parts could interfere with lower check
- Dual checks are not better than single for erosion resistance
- However, dual checks may still offer sealing redundancy if **fluids are clean**



ALRDC.COM



2024 GAS LIFT WORKSHOP

Sand Erosion Results – Passing

Make	Model	Size	Change	Assembly	Rnd	Date	Pass?		
							Water	Sand 0.6	Sand 1.0
A	A.0	1	-	Single	1	Jul-23	Yes	No	-
	A.1	1	Coating	Single		Jul-23	Yes	No	-
	A.2	1	Coating	Single		Jul-23	Yes	No	-
	A.0	1	-	Dual		Jul-23	-	No	-
	A.1	1	Coating	Dual		Jul-23	-	No	-
	A.2	1	Coating	Dual		Jul-23	-	No	-
B	A	1	-	Single	1	Mar-23	Yes	No	-
	B	1	Materials	Single	2	Aug-23	Yes	No	-
	C	1	Geometry	Single		Feb-24	Yes	No	-
	D	1	Geometry	Single	3	Feb-24	Yes	Yes	No
	E	1	Geometry	Single		Feb-24	No	-	-
C	A	1	-	Single	1	Mar-23	No	-	-
	B	1	Pressure	Single		Mar-23	Yes	No	-
	C	1	Geometry	Single		Mar-23	Yes	No	-
D	A.0	1	-	Single	1	Nov-23	Yes	No	-
	A.1	1	Coating	Single		Nov-23	Yes	No	-
	A.0	1.5	-	Single		Nov-23	Yes	Yes	-
E	A	1	-	Single	1	Feb-23	Yes	No	-
	B	1	Geometry	Single	2	Jul-23	Yes	No	-
	B	1.5	Geometry	Single		Aug-23	Yes	Yes	Yes

Success...partially

- 3 passed the 0.6 bbl/min test, but...
- Two were 1.5" checks!
- These were "bonus" tests – but they did show something interesting
- More on the 1.0" check later...



ALRDC.COM

1.5" GLVs in EM Bakken
7" csg. have had minimal
solids-related issues

1" Model D.A.0

Water Testing – 1" vs. 1.5" Checks, 1.0 bbl/min

1.5" Model D.A.0



0.32" ID = **167.5 ft/s**

Smaller flow path = **2.5x** higher velocity = More severe erosion!


0.50" ID = **68.6 ft/s**



2024 GAS LIFT WORKSHOP

Model B.D

Sand Erosion Results – 1" Passing at 0.6 bbl/min




No need to punch the dart free between passes!

ALRDC.COM



2024 GAS LIFT WORKSHOP

Sand Erosion Results – 1" Passing at 0.6 bbl/min



Worn, but functional. Improved materials, shielded spring

ALRDC.COM



2024 GAS LIFT WORKSHOP

Model B.D

Sand Erosion Results – 1" Almost at 1.0 bbl/min



Component debris led to housing failure following 300 bbl check

ALRDC.COM



2024 GAS LIFT WORKSHOP

Sand Erosion Results – 1" Almost at 1.0 bbl/min



- Flow ports worn but intact, seal pad failed
- Dart, post, and spring in good condition
- Internal blockage led to housing ID point erosion
- Almost survived...


Summary and Next Steps

Summary

- Fine frac sand is difficult to remove from producers
- GLVs and API 19G2 reverse flow check testing were not designed for wells with entrained sand
- >20 checks were tested with 1% sand in a modified API procedure
- Only **one** survived the 400 bbl, 0.6 bbl/min test...so far
- 1.5" checks are more resistant to erosion, 5Ks and dual checks are not

Next Steps

- Geometry and material changes have shown the most promise, upgrades could also be applied to offshore / critical service 1.5" GLVs
- Keep improving until 1 bbl/min test is passed...or the flow loop wins!
- (Keep recommending 7" casing—1.5" GLVs and SPMs are nice)



1% wt sand content
in 5 gal of mixture



2024 GAS LIFT WORKSHOP

Questions?



ALRDC.COM



Copyright

- Rights to this presentation are owned by the company(ies) and/or author(s) listed on the title page. By submitting this presentation to the Gas Lift Workshop, they grant to the Workshop, and the Artificial Lift Research and Development Council (ALRDC) rights to:
 - Display the presentation at the Workshop.
 - Place the presentation on the www.alrdc.com web site, with access to the site to be as directed by the Workshop Steering Committee.
 - Place the presentation for distribution and/or sale as directed by the Workshop Steering Committee.
- Other uses of this presentation are prohibited without the expressed written permission of the company(ies) and/or author(s).





Disclaimer

The following disclaimer shall be included as the last page of a Technical Presentation or Continuing Education Course. A similar disclaimer is included on the Gas Lift Workshop webpage.

The Artificial Lift Research and Development Council and its officers and trustees, and the Gas Lift Workshop Steering Committee members, and their supporting organizations and companies (here-in-after referred to as the Sponsoring Organizations), and the author(s) of this Technical Presentation or Continuing Education Course and their company(ies), provide this presentation and/or training material at the Gas Lift Workshop "as is" without any warranty of any kind, express or implied, as to the accuracy of the information or the products or services referred to by any presenter (in so far as such warranties may be excluded under any relevant law) and these members and their companies will not be liable for unlawful actions and any losses or damage that may result from use of any presentation as a consequence of any inaccuracies in, or any omission from, the information which therein may be contained.

The views, opinions, and conclusions expressed in these presentations and/or training materials are those of the author and not necessarily those of the Sponsoring Organizations. The author is solely responsible for the content of the materials.

The Sponsoring Organizations cannot and do not warrant the accuracy of these documents beyond the source documents, although we do make every attempt to work from authoritative sources. The Sponsoring Organizations provide these presentations and/or training materials as a service. The Sponsoring Organizations make no representations or warranties, express or implied, with respect to the presentations and/or training materials, or any part thereof, including any warranties of title, non-infringement of copyright or patent rights of others, merchantability, or fitness or suitability for any purpose.